


Belzona For Mud Pumps



Severe wear on the pump casing.



Forming technique and Belzona® 1311 (Ceramic R-Metal) used to rebuild the intake.



Two coats of Belzona® 1321 (Ceramic S-Metal) applied.

STATISTICS

CUSTOMER

Offshore Oil Drilling Platform,
Gulf of Mexico

APPLICATION DATE

July 1995

SUBSTRATE

Cast iron

PRODUCTS

Belzona® 1311
(Ceramic R-Metal)
Belzona® 1321
(Ceramic S-Metal)

APPLICATION SITUATION

Mud pumps, casings and wear plates.

PROBLEM

Severe erosion.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflets CEP-3 and CEP-5

BELZONA FACTS

The use of Belzona doubled the life of the casing and saved the replacement costs. Originally, the equipment lasted 3 months before being discarded and now it lasts 6 months and can be refurbished again and again.