

## Belzona® Repair to Power Plant Coal Belt



Hole in the belt being prepared



Preparation completed



Completed application



Completed application

### STATISTICS

#### CUSTOMER

Power Station,  
Missouri, USA

#### APPLICATION DATE

2007

#### SUBSTRATE

Rubber

#### PRODUCTS

Belzona® 2111  
(D&A Hi-Build Elastomer)

#### APPLICATION SITUATION

One of a series of large belts used to bring coal from the coal yard to the plant.

#### PROBLEM

Belt developed a large burn hole. This rendered the belt unusable until fixed.

#### APPLICATION METHOD

Belt was repaired according to Belzona System Leaflet SHM-1

#### BELZONA FACTS

The company that usually repairs their belts takes a long time to respond to service requests and are very expensive. They needed the repair completed quickly. The belt was repaired in a matter of hours and the plant now uses Belzona for all belt repairs.