

Quarry Belt Repair



Large Sand Belt



600mm gash in the belt

STATISTICS

CUSTOMER

Local Depot,
Manchester, UK

APPLICATION DATE

June 2000

SUBSTRATE

Rubber

PRODUCTS

Belzona[®] 2311
(SR Elastomer)

APPLICATION SITUATION

Sand Belt

PROBLEM

600 mm (23 inch) tear in the belt

APPLICATION METHOD

Application was carried out in accordance with Belzona[®] Know-How System Leaflet SHM-1

BELZONA FACTS

The belt performed well until the plants closing in 2004.