

Belzona Protects Stadium*Overall view of stands**Close up of typical damaged block**Completed south wall area**Completed north wall area***STATISTICS****CUSTOMER**

St. Louis University,
St. Louis, Missouri, USA

APPLICATION DATE

April 2005

SUBSTRATE

Stone

PRODUCTS

Belzona® 3111
(Flexible Membrane)

APPLICATION SITUATION

Stone wall caps

PROBLEM

Wall caps had deteriorated to the point of either needing repairing or replacing.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona® Know-How System Leaflet RPA-11.

BELZONA FACTS

Replacement cost in this situation was astronomical; the Belzona solution offered a cost effective alternative. The Belzona 3111 was tinted to match the color of the original stone.