

Tank Roof Repair



Damaged tank roof



Preparation of roof surface



Application of Belzona

STATISTICS

CUSTOMER

Drinking water supplier,
Portugal

APPLICATION DATE

August 2004

SUBSTRATE

Concrete

PRODUCTS

Belzona® 3111
Belzona® 9311
Belzona® 3911

APPLICATION SITUATION

Drinking water supply tank

PROBLEM

The roof was badly deteriorated

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Systems Leaflet RPA-1.

BELZONA FACTS

The client was impressed by the performance of Belzona on other applications in the region. The products excellent UV resistance, weatherproofing and long life meant that this was an economical long term repair.