

Belzona Seals Insulator Leaks



Surface preparation in progress



Surface preparation by grit blasting completed



Completed application

STATISTICS

CUSTOMER

Power Plant,
British Columbia, Canada

APPLICATION DATE

August 2003

SUBSTRATE

Porcelain and Aluminum

PRODUCTS

Belzona® 2121
(D&A Hi-Coat Elastomer)

APPLICATION SITUATION

Power Line Insulators

PROBLEM

Seal within insulators eroded and as a result oil leakage began to occur.

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet GSS-3.

BELZONA FACTS

Belzona products have been used for many of these types of sealing applications with tremendous success.