


Belzona Repair of Access Ramp and Steps



Worn steps were a health and safety hazard



Prepared surface



Surface rebuilt with Belzona® 4131



Completed project

STATISTICS

CUSTOMER

Local Council,
United Kingdom

APPLICATION DATE

November 2004

SUBSTRATE

Old concrete

PRODUCTS

Belzona® 4131
Belzona® 4411
Belzona® 5231

APPLICATION SITUATION

Heavily worn steps and disabled access ramp.

PROBLEM

Much foot traffic and heavy weathering caused the steps and disabled access ramp of these public toilets to become damaged and worn. An inspection of the ramps according to the Disability Discrimination Act (DDA) found them to be unsafe and not compliant.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The use of Belzona® products was requested by the council in order to give a fast, long life, cost effective repair. The ability to bond and build up old concrete meant that the steps did not have to be completely removed and rebuilt. This ensured that the toilets would comply to the DDA standards. These heavily used toilets were quickly reopened to the public.