

Belzona Repairs to Rooftop Exhaust Ducting



First duct joint



Close up of first joint repair



Second joint repair

STATISTICS

CUSTOMER

Pet Food Manufacturer,
MO

APPLICATION DATE

April 2007

SUBSTRATE

Galvanized Metal

PRODUCTS

Belzona[®] 2211
(MP Hi-Build Elastomer)

APPLICATION SITUATION

Rooftop exhaust ductwork

PROBLEM

Joints were leaking allowing escape of unpleasant gases into the neighborhood leading to many complaints.

APPLICATION METHOD

Application carried out using a modified Belzona System VPF-11a

BELZONA FACTS

Years of successful repairs, some of them very difficult, gave client the confidence to proceed with Belzona repairs.