


Classic Pump Refurbishment with Belzona



Rebuilding profiles underway



Another view of profiles



Completed application

STATISTICS

CUSTOMER

Copper manufacturer,
Belgium

APPLICATION DATE

November 2005

SUBSTRATE

Steel

PRODUCTS

Belzona® 1321
Belzona® 1111

APPLICATION SITUATION

Pump housing.

PROBLEM

Erosion/corrosion from constant water flow within the pump caused erosion in critical parts of the housing.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-2 & -5.

BELZONA FACTS

Belzona was chosen because the customer had had numerous good experiences with Belzona on previous applications in pumps.