


# **CASE**STUDY

# Belzona Provides Sea Water Filter Protection



Main body of filter



Vertical view showing protected flange faces



Exit nozzle coating



Individual small bore nozzle coating

## **STATISTICS**

## **CUSTOMER**

Danish Oil Operator

#### **APPLICATION DATE**

Various since 2003

#### **SUBSTRATE**

Cast Steel

#### **PRODUCTS**

Belzona® 1111 Belzona® 1321

#### **APPLICATION SITUATION**

Sea Water Filter System on offshore oil production platform.

#### **PROBLEM**

Conventional coatings were failing around the sealing faces and nozzle areas.

#### **APPLICATION METHOD**

The application was carried out using a combination of Belzona Know-How System Leaflets TCC-3 and VPF-13.

## **BELZONA FACTS**

The success of the Belzona repair and protection system has resulted in numerous further filters being coated since 2003.

© Copyright 2007 by Belzona International, Ltd. All rights reserved. No part of this work covered by the copyrights herein may be reproduced or used in any form or by any means - graphic, electronic or mechanical including photocopying, recording, taping, or information storage and retrieval systems - without written permission of the publisher.