

Belzona Protects Mixing Tank



Bare unprotected mixing tank



Surface prepared and holes patched with Belzona® 4111



First coat of Belzona® 5811 being applied



Final coat Belzona® 5811 applied

STATISTICS

CUSTOMER

Dairy,
Oklahoma, USA

APPLICATION DATE

March 2006

SUBSTRATE

Concrete

PRODUCTS

Belzona® 4111
Belzona® 5811

APPLICATION SITUATION

During expansion, the large dairy constructed a new water plant to treat their own water (average 400,000 GPD).

PROBLEM

Customer needed protection on their KMnO_4 (Potassium Permanganate) mixing tank.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System leaflet TCC-15.

BELZONA FACTS

Customer choose Belzona based on success of previous applications.