

Typical Chiller Repair With Belzona




The corroded tube sheet



Rebuilding the division bars



End cover being coated



Tube sheets were protected by Belzona® 1321

STATISTICS

CUSTOMER

Five star hotel,
Egypt

APPLICATION DATE

March 2003

SUBSTRATE

Steel

PRODUCTS

Belzona® 1311
Belzona® 1321

APPLICATION SITUATION

Chiller unit from the hotels air conditioning plant.

PROBLEM

Corrosion of tube sheet and the end covers.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets HEX-1,-2 & -3.

BELZONA FACTS

This is a many times repeated Belzona Application to chiller units. Both corroded tube sheets and end covers were perfectly rebuilt and provide long term corrosion protection.