

## Expansion Joint at Hospital Sealed with Belzona



View of joint with kick plate removed



Application of Belzona® 4111



Application of Belzona® 2221



Completed application

### STATISTICS

#### CUSTOMER

Hospital,  
Missouri, USA

#### APPLICATION DATE

2007

#### SUBSTRATE

Concrete

#### PRODUCTS

Belzona® 4111  
Belzona® 2221

#### APPLICATION SITUATION

Expansion joints in corridor in need of repair.

#### PROBLEM

Expansion joints in the hospital had become a tripping hazard.

#### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and -6.

#### BELZONA FACTS

The hospital needed a fast-curing and reliable method for repairing expansion joints that were creating trip hazards for patients.