



Belzona Protects Tube Sheet and Tubes



The corroded tube sheet



Sketch of the repairs



Loading insertions



Application after 3 years
(still like new)

STATISTICS

CUSTOMER

Steel mill,
Slovakia

APPLICATION DATE

2003

SUBSTRATE

Steel

PRODUCTS

Belzona® 1131
Belzona® 1321
Belzona® 1341
Belzona® 5811

APPLICATION SITUATION

Condenser tube sheets and tubes.

PROBLEM

Corrosion problems were beginning on the tube sheet and inlet tubes (50 mm).

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet HEX-1, HEX-2 & HEX-3.

BELZONA FACTS

Belzona provided long term protection, increasing the life of the tube sheet and also inlet tubes, decreasing other repair and maintenance costs. Inspection after 3 years showed excellent protection being maintained.