BELZONA® PROTECTS CAUSTIC CONTAINMENT AREA

CUSTOMER

Power Plant, Alabama USA

APPLICATION DATE

December 2007

APPLICATION SITUATION

Caustic Containment Area in water treatment plant.

PROBLEM

Customers Caustic Containment Area coating had failed and needed a new impervious coating installed.

PRODUCTS

Belzona® 5811 (Immersion Grade)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Old coating was removed using high pressure water blasting. Belzona® 5811 was applied to both containment and tank stands.

BELZONA FACTS

Belzona has been used for years in many of Alabama Powers Plants. Customer trusted the product and longevity of previous applications.

PICTURES

- 1. Containment before old coating removed
- 2. Containment after old coating removed
- 3. & 4. Completed application









www.belzona.com



e: belzona@belzona.com

e: belzonacanada@belzona.com