

## BELZONA® PROTECTS CHEMICAL CONTAINMENT AREA

### CUSTOMER

Food Processing plant, France

### APPLICATION DATE

June 2003

### APPLICATION SITUATION

Chemical containment area

### PROBLEM

Heavy deterioration of the concrete due to leakage and contamination during maintenance operations. The integrity of the structure was compromised.

### PRODUCTS

Belzona® 4111 (Magma Quartz)

Belzona® 4311 (Magma CR1)

### SUBSTRATE

Concrete, Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Special attention given to shimming and protecting base of support steelwork.

### BELZONA FACTS

Area brought up to standard to meet required regulations. Additional protection for supports. Repairs easily carried out if required. Durable: During the last inspection in 2009, the containment area was in perfect condition.

### PICTURES

1. View before repairs
2. View of the tank supports
3. View after shimming
4. Application completed with Belzona® 4311 applied



[www.belzona.com](http://www.belzona.com)



**Europe & Africa**  
Belzona Polymerics Ltd.  
Harrogate, UK  
t: +44 1423 567641  
f: +44 1423 505967  
e: [belzona@belzona.co.uk](mailto:belzona@belzona.co.uk)

**The Americas**  
Belzona Inc.  
Miami, FL USA  
t: +1 (305) 594-4994  
f: +1 (305) 599-1140  
e: [belzona@belzona.com](mailto:belzona@belzona.com)

**Canada**  
Belzona Canada Inc.  
Richmond, ON Canada  
t: +1 (905) 737-1515  
f: +1 (905) 737-1597  
e: [belzonacanada@belzona.com](mailto:belzonacanada@belzona.com)

**Asia & Oceania**  
Belzona Asia Pacific  
Chonburi, Thailand  
t: +66 38 491031  
f: +66 38 491102  
e: [belzona@belzona.cn](mailto:belzona@belzona.cn)

**China**  
Belzona Hong Kong  
Hong Kong, China  
t: +852 3753 7505  
f: +852 3753 7510  
e: [belzona@belzona.hk](mailto:belzona@belzona.hk)

  
**BELZONA®**  
Repair • Protect • Improve